

	A	B	C	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments, not form fields)					
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7		FEDNAV INTERNATIONAL LTD	FEDERAL WESER	MARSHALL ISLANDS	9229972	17-Jun-14

	G	H	I	J
1				
2				
3	7	8	9	10
4				
5				
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption
7	HAMBURG	ANTWERP, BECANCOUR, SOREL, ERIE, BURNS HARBOR, THUNDER BAY	ANTWERP	N/A

	K	L	M	N	O
1					
2					
3	11	12	13	14	15
4					
5					
6	Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil
7	N/A	1	THE VESSEL IS PRESENTLY IN THE ECA	12:00	2.40%

	P	Q	R	S	T
1					
2					
3	16	17	18	19	20
4					
5					
6	Projected Hours on Main Propulsion	Name of First POC	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC
7	16	THUNDER BAY	NO	NO	1

	U	V	W	X	Y
1					
2					
3	21	22	23	24	25
4					
5					
6	Name of Second POC	Compliant Fuel Oil at Second POC?	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?
7	PORT COLBORNE	YES	YES	1	2-Sep-14

	Z	AA	AB	AC	AD
1					
2					
3	26	27	28	29	30
4					
5					
6	Time of Exit from ECA?	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?
7	12:00 YES		6	33 YES	

	AE	AF	AG	AH
1				
2				
3	31	32	33	34
4				
5				
6	Number of Submitted Reports	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number
7	7	DONALD PINKERTON	dpinkerton@fednav.com	514-878-6439

	AI	
1		
2		
3		35
4		
5		
6	Description of Actions to Achieve Compliance	
7	COMPLIANT LOW SULPHUR FUEL WAS UNSUCCESSFULLY SOUGHT OUT ATTHUNDER BAY. COMPLIANT FUEL WILL BE SUPPLIED AT PORT COLBORNE, ONTARIO	